



MARITIME SAFETY AUTHORITY
OF NEW ZEALAND

Te Mana Ārai Hauata Moana o Aotearoa

Reduced steering

Incat 050

4/01/2000

Inbound, approaching the Wellington bar at about 20 knots to the west of the leads with a following sea and ebb tide. The conditions caused the vessel to yaw and so the Master turned around and approached at 28 knots on the leads. The second attempt was successful.

Report Completion Date: 20/01/2000

Key Events

1.1 At 0715 hours on Tuesday 4.1.00, the passenger ferry **Incat 050**, known as **Topcat**, sailed from Wellington to Picton in seas that the Master **estimated** had a significant wave height of **between 3 and 4m** with the wind **from** the south.

1.2 At 1015 hours, the vessel was scheduled to leave Picton but was a little late, having lost time on **the** previous passage.

1.3 At 13 15 **hours**, **the** vessel was scheduled to leave Wellington **but was** a little late **due to** a heavy loading at Picton and the accumulation of lost time as a result of the Master having slowed down on previous trips to ease the vessel's movement in a **southerly** wind.

1.4 At 1642 hours, Metservice issued a forecast for **Topcat**, received at about this time on the bridge of the vessel, indicating that at 1700 hours the significant wave height would be **4.5m** easing to **3.5m** on Wednesday morning.

1.5 At 1700 hours, the **vessel** left Picton, forty **five** minutes behind schedule largely due to an accumulation of lost time throughout the **day**.

1.6 At about 1700 hours, the 2030 hours sailing **from** Wellington was **cancelled** by **the** Master who telephoned the **Marine** Manager to inform him of his decision. **The** Marine Manager **informed** the Terminals and **the** CEO. The sailing was cancelled **due to** the **4.5m** significant wave height. **The** Marine Manager stated that the sailing was cancelled owing to **the** forecast **4.5m significant** wave height which may have been generated by the time of the 2030 hours sailing, **as the wind was** continuing to build."

1.7 At 1817 hours, the Master **called** Beacon Hill Radio station giving his **ETA** as 1915 hours and he received an acknowledgement that **included** an estimate of the significant wave height as being **"3.5m at the entrance"**.

1.8 On arriving at Sinclair **Head**, the Master noticed a deterioration in **the** weather. According to the Marine Manager, the waves were at a significant wave height of about 4m at this **junction**. He obtained this **information** from **the** Master at his debriefing.

1.9 At a position **3 nautical miles** south of Barrett Reef Buoy, the Master altered course from **070°(T)** to **040°(T)**. He continued to bring the vessel round to port until, at a point south of **Pencarrow Head Light House** but slightly west of the leading lights, he had reached **025°(T)**.

1.10 As the vessel approached Pencarrow **Head Light House**, course **was** steadied on **020°(T)** and the speed was estimated by the **Master** to have been about 20 knots,

1.11 At **1904 hours**, a **larger than** average swell caused a severe port yaw and a **further** yaw back to starboard,

1.12 'With the vessel in position 41° 21.7' S 174° 50.1' E (about 0.47 nautical miles **from** Barrett Reef Buoy), the Master aborted **his** attempt to **enter** the **harbour** and continued **the turn** to starboard and steadied on a course out of **the** harbour **until he** was about 1.5 nautical miles south of **Barrett** Reef Buoy. At that point he **turned** round again and lined up for a second attempt at entering **the** harbour.

1.13 He increased the speed to 28 knots and found the vessel more manageable on this second approach. The vessel entered **harbour satisfactorily** at this attempt.

Key Conditions

2.1 The Master was David J. **Cass**. He holds a **Foreign** Going Master's Certificate No. 2357 issued on **6.1.75** in New Zealand. He holds a High Speed Navigation Certificate issued on 6.5.99 and has accumulated 9 months **service** on high speed craft.

2.2 The vessel is a high speed, so called "wave piercing" catamaran **operated** by **Fast** Cat Ferries Ltd and registered in Nassau, Bahamas. Her Permit to Operate limits her operation to the route **between** Wellington and **Picton** and she is to be no more than 100 miles **from** a port of refuge.

2.3 The Permit to Operate High Speed Craft was issued under the authority of the **Commonwealth** of the Bahamas by **the** Maritime Safety Authority of New Zealand on 27 August 1999 and this was valid to **15** February 2000. It contained a clause that "the craft **shall** not put to sea if **the** significant wave height on passage exceeds or is predicted to exceed **4.0 metres**."

2.4 According to the Master, the significant wave height had, in his opinion, been less **than** 4m between **Sinclair** Head and Tory Channel entrance consistently throughout the day.

2.5 At 1042 hours, the **Metservice** had issued a **forecast** for **Topcat** that had the significant wave height was "About **4m**, slowly rising to **4.5m** throughout the day."

2.6 At 1642 hours, (18 minutes before the vessel's departure **from Picton**) the **Metservice** issued a forecast for **Topcat** that the significant wave **height** as "**4.5m** easing to **3.5m** Wednesday morning."

2.7 The Master was thus technically in breach of this clause because of the **4.5m** forecast at 1642 hours. He claims that his experience of the wave height on his previous voyages that day was a more reliable guide. Indeed, the report **from** Beacon Hill at 18 17 hours, that the height of the waves at the entrance were **3.5m**, tends to reinforce his point.

2.8 High tide at **the entrance** to Wellington **Harbour** was predicted to be at 1616 hours NZDT and there was **southerly** wind rising to 35 knots forecast by **Metservice** for the night of Tuesday 4 **January**. So at 1904 hours, when the **vessel** was abeam of Barrett Reef Buoy and not handling as the Master would have liked, the **ebb** tide against the southerly wind, the limited depth at the **harbour** entrance at that point and the speed of 20 **knots**, all conspired to produce **very** difficult **conditions**.

2.9 The normal course on approach to Wellington is 090°(T) and then a **turn** to port onto the leads. The Master took the **070°(T)** course, having made due **allowance** by **coming further** south of **Sinclair** Head, to ease the uncomfortable ride that the weather was giving the passengers. He slowed down to 20 knots for the same reason.

2.10 There **were** 580 passengers on board. A **small** number of them complained to the Maritime Safety Authority that they were not informed of the reason for **the** vessel having turned round. In fact, **10** passengers **contacted** the Maritime Safety Authority. Five of **them** complained that they were not **informed** of what was happening and one of those questioned whether the vessel should **have sailed though admitting** that she had limited knowledge. One was critical of the vessel's position **when** she **turned**. The remaining four were appreciative of the way the Master handled the vessel.

2.11 There **was** no **damage** sustained to the boat and nobody was injured.

2.12 There **were** no mechanical or technological failures.

2.13. The **Metservice** weather report for Tranzrail contains information from the waverider buoy that **Tranzrail** lease **from** the National Institute of Water and Atmospheric Research relating to the significant **wave** height and the highest wave **in** the last **4** hours, Specifically, the 1649 hours report has a **significant** wave height of **4.4m** and a highest wave of **7.1m**. This information is not transmitted to **Topcat**.

2.14 The **Marine Manager** produced significant wave height **figures** comparing **MetService** forecasts with observations from **Incat 050** over a **36** hour period during 2 and 3 January. The **latter** are **established** by a combination of visual estimation and a recording device on the vessel. The wave heights estimated on the part of the **MetService** appear to vary by amounts from **0.2m** to **0.75m** above the operator's own estimates.

26

Contributing Factors

3.1 The ebb tide against the southerly wind estimated at 1600 hours by Beacon Hill Radio Station staff to have been blowing from a direction of **200°(T)** at 22 to 44 knots.

3.2 The significant wave height of approximately **4m**.

3.3 The reducing depth at the harbour entrance at a point abreast of **Barrett** Reef.

3.4 The speed of 20 knots.

3.5 The non-availability of useful wave height information to **Incat 050** from the wave rider buoy.

3.6 The lack of confidence that **Incat 050** Masters have in the **Metservice** wave height forecasts that are dependent, *inter alia*, on computer generated models. This uncertainty is **underlined** when the Masters themselves have recently experienced the **actual** weather as differing from that **forecast** in the affected **area**.

Causes

Human Factor

- | | | |
|---|---|--|
| <input type="checkbox"/> Fake to comply with regulations | <input type="checkbox"/> Drugs and Alcohol | <input type="checkbox"/> Overloading |
| <input type="checkbox"/> Failure to obtain ships position or course | <input type="checkbox"/> Fatigue | <input type="checkbox"/> Misconduct/Negligence |
| <input type="checkbox"/> Improper watchkeeping or lookout | <input type="checkbox"/> Physiological | <input type="checkbox"/> Error of Judgement |
| <input type="checkbox"/> Lack of knowledge | <input checked="" type="checkbox"/> Ship Handling | <input type="checkbox"/> Other... |

Environmental Factor

- | | | | |
|---|---|------------------------------------|--|
| <input checked="" type="checkbox"/> Adverse weather | <input type="checkbox"/> Debris | <input type="checkbox"/> Ice | <input type="checkbox"/> Navigation Hazard |
| <input type="checkbox"/> Adverse current | <input type="checkbox"/> Submerged object | <input type="checkbox"/> Lightning | <input type="checkbox"/> Other... |

Technical Factor

- | | | | |
|---|---|---|-----------------------------------|
| <input type="checkbox"/> Structural failure | <input type="checkbox"/> Wear and tear | <input type="checkbox"/> Steering failure | <input type="checkbox"/> Other... |
| <input type="checkbox"/> Mechanical failure | <input type="checkbox"/> Improper welding | <input type="checkbox"/> Inadequate firefighting/lifesaving | |
| <input type="checkbox"/> Electrical failure | <input type="checkbox"/> Inadequate maintenance | <input type="checkbox"/> Insufficient fuel | |
| <input type="checkbox"/> Corrosion | <input type="checkbox"/> Inadequate stability | | |

4.1 The ebb tide against a southerly wind and the reducing depth at the Wellington Harbour entrance conspired to cause the **Incat 050** to yaw in **such a** manner as to persuade the Master to **abandon** his **first** attempt to enter and to make a second attempt at a different speed and on a different approach course.

Opinions and Recommendations

5.1 The three **Incat 050** Masters should meet as a **matter** of routine on a regular, say monthly, basis to share their experiences and discuss the most beneficial solutions to any **difficulties** or problems that have arisen since **the** last meeting. Such incidents should be recorded in the deck log book when they occur and the entries used as a **basis** for discussion. Sharing **weather** information with Tranzrail ferry Masters should be encouraged by the **managements** of each **organisation** for the mutual benefit of **all**.

5.2 **Topcat** Management to explore the possibility of obtaining more accurate significant wave height information where it is critical at the Wellington **Harbour** entrance. **e.g.** Obtain their information **from** another **source** and **liaise** with **Tranzrail**, the Port Company and Wellington Regional Council to determine if wave under buoy information can be **made** available to **all** and to explore the **feasibility of moving** the buoy to a position **closer** to **the** critical area.

5.3 The Master did not inform the passengers **that** he had aborted his first attempt to enter the **harbour** but that **they** should not be **concerned** for their safety because he had matters under control. Had he kept them informed it would have allayed the fears of those passengers who were frightened and in any case should have been a matter of routine. Passenger **welfare** is a safety concern - it is not simply a public relations matter. It is recommended that **Topcat** Management **develop** standard phrases and put in place procedures as to when these phrases are to be used and by whom so that the Master may devote his or her attention to the task of handling the ship

5.4 At the next renewal or re-issue of the **Permit** to Operate, the Operations Division of the **Maritime Safety Authority** should **re-examine** the wording of the Permit to Operate and amend it so that it is made clear **exactly** how the significant wave height is to be predicted and by whom. Further, that a **clause** be inserted into **the** Permit to Operate to indicate **that** the Master will risk prosecution under section **65** of the **Maritime Transport Act** if he sails **from** port when the significant wave height stipulated in **the** Permit to Operate is exceeded.

5.5 It is **frequently** possible during the day to alter course to ameliorate the effects **of** above average wave trains when they can be identified visually. It came to light during the interviews that the Masters **find** it difficult to avoid such wave trains when they cannot see **them** coming at night.

Although it was not a factor in this incident, it is recommended that when the Permit to Operate is next renewed by the Operations Division of the **Maritime Safety Authority**, they consider adjusting the significant wave height limit referred to in **clause** 12.3 of **the** Permit to account for the lack of visual warning of **approaching** waves or for **Topcat** and **Tranzrail** managements to research the practicality of **infra** red enhanced visual aids being provided for the Masters and Officers of the Watch on fast ferries, This to be done in consultation with the Masters of both **Tranzrail** and **Topcat** fast ferries.